

Bath Thermometer Sticker (Sea & Land Series) SBT-02

Features

1. Sticker.
2. Easy to read.
3. 3 indicators.
4. Space less.
5. No battery required.

IDEAL
36°C-38°C



COLD
Under 38°C

IDEAL
36°C-38°C

HOT
Above 38°C

Apply it in water temperature
between 34° C~40° C



0+
mos.



ISO13485

Specification

Temperature Range: cold (36>), Ideal (36 - 38), H (<38)

Snow flake appears when temperature 37.5° C has been reached ,

smile face shows the best temperature for bathing.

Size: 9.2 x 3.6 cm

Readable icons displayed on the thermometer.

6 different patterns to choice.

Materials : PP / Liquid Crystal



KenHealth
www.kenhealth.biz